

## S.C. Occupational Safety and Health Administration

## 25 MOST FREQUENTLY CITED GENERAL INDUSTRY

## January 1, 2011- December 31, 2011

Rank	# Cited	Standard	Hazard Description
1	103	1910.1200(e)(1)	No written Hazard Communication Program
2	64	1910.1200 (h)(1)	Inadequate training on hazardous chemicals
3	41	1910.1200(e)(1)(i)	No list of hazardous chemicals
4	41	1910.1200(g)(1)	No MSDS for hazardous chemicals No grounding provision for cord and plug connected appliances used in damp or wet locations
5	38	1910.304(g)(6)(vi)(c)(5)	
6	37	1910.212(a)(1)	Machinery not properly guarded
7	28	1910.215 (b)(9)	Missing tongue-guard on grinder
8	28	1910.305 (b)(1)(ii)	Unused openings in cabinets, boxes, and fittings not effectively closed
9	24	1910.147 (c)(6)(ii)	No certification of periodic inspections performed
10	24	1910.178(I)(4)(iii)	No evaluation of forklift operator's performance conducted at least every 3 years
11	22	1910.134(e)(1)	No medical evaluation provided prior to use of respirator
12	22	1910.147 (c)(1)	No Hazardous Energy Control (Lock Out Tag Out) Program
13	21	1910.1200(f)(5)	No Label on hazardous chemical containers
14	20	1910.178 (I)(1)(i)	No forklift operator training
15	19	1910.134(k)(6)	Failed to provide basic advisory information on respirators
16	19	1910.305 (b)(2)(i)	No covers on pull boxes, junction boxes and fittings
17	18	1910.147 (c)(4)(ii)	No specific hazardous energy control (Lock Out Tag Out) procedures
18	17	1910.23(c)(1)	Failed to guard every open-sided floor or platform
19	13	1910.147(c)(6)(i)	Failed to conduct periodic inspection of the energy control procedures
20	13	1910.303(g)(2)(i)	Failed to guard live parts of electric equipment operating at 50 volts or more No grounding provision for cord and plug-connected tools used in damp or wet locations
21	13	1910.304(g)(6)(vi)(c)(7)	
22	13	1910.334(a)(3)(ii)	Failed to prohibit the use of adapters which interrupt grounding connections
23	12	1910.38(b)	Failed to implement emergency action plan in writing accessible to employees
24	12	1910.147(c)(4)(i)	Failed to develop, document, and utilize any LOTO procedures
25	12	1910.212(a)(5)	Failed to guard fan blades