



SC Occupational Safety and Health Administration

25 MOST FREQUENTLY CITED GENERAL INDUSTRY STANDARDS

January 1, 2013- December 31, 2013

Rank	# Cited	Standard	Hazard Description
1	51	1910.304(g)(6)(vi)(c)(5)	No grounding provision for cord and plug-connected appliances used in damp or wet locations
2	46	1910.212(a)(1)	Machinery not properly guarded
3	39	1910.305(b)(2)(i)	No covers provided for pull boxes, junction boxes, and fittings
4	35	1910.215(b)(9)	Missing tongue guard on grinder
5	32	1910.305(b)(1)(ii)	Unused openings in cabinets, boxes, and fittings not effectively closed
6	24	1910.304(g)(5)	No permanent, continuous, and effective path to ground
7	22	1910.1200(h)(1)	Inadequate training on hazardous chemicals
8	22	1910.334(a)(3)(i)	No grounding conductor on a flexible cord
9	21	1910.333(a)	No electrical safety-related work practices
10	20	1910.1200(e)(1)	No written hazard communication program
11	20	1910.1200(e)(1)(i)	No list of hazardous chemicals
12	20	1910.242(b)	Compressed air over 30 p.s.i. used for cleaning purposes
13	19	1910.147(c)(1)	No Hazardous Energy Control (Lock Out Tag Out) Program
14	18	1910.178(l)(1)(i)	No forklift operator training
15	18	1910.219(e)(3)(i)	No guard on vertical and inclined belts
16	16	1910.212(a)(5)	No guard on fan blades less than seven (7) feet above the floor or working level
17	15	1910.212(a)(3)(ii)	No guard provided on point of operation of machines
18	15	1910.23(c)(1)	No guard on open-sided floor or platform above adjacent floor or ground level
19	15	1910.242(a)	Employer failed to be responsible for the safe condition of tools and equipment
20	15	1910.304(g)(6)(vi)(c)(8)	No grounding provision for portable hand lamps used in damp or wet locations
21	15	1910.334(a)(3)(ii)	No attachment or cheater plugs used which prevent continuity of equipment
22	14	1910.23(c)(1)	No guard on open-sided floor or platform above adjacent floor or ground level
23	14	1910.219(f)(3)	No guard for sprocket wheels and chains less than seven (7) feet above the floor or platform
24	14	1910.219(i)(2)	No guard on mechanical transmission on shaft couplings
25	14	1910.304(b)(3)(i)	No GFCI protection in bathrooms or on rooftops

January 1, 2013- December 31, 2013