

S.C. Occupational Safety and Health Administration

25 MOST FREQUENTLY CITED CONSTRUCTION STANDARDS

January 1, 2010- December 31, 2010

Rank	# Cited	Standard	Hazard Description
1	156	71- 112(a)	General Duty Clause
2	86	1926.451(g)(4)(i)	Inadequate Guardrails On Open Sides And Ends Of Scaffold Platforms
3	75	1910.1200 (e)(1)	No Written Hazard Communication Program
4	70	71-340	Recordkeeping logs not provided within 4 business hours when requested
5	70	1926.501(b)(13)	No Fall Protection for Employees Working Above 6 Feet in Residential Construction
6	63	1926.501(b)(1)	Fall Protection – Unprotected Sides And Edges/Residential Construction
7	56	1926.453 (b)(2)(v)	No Body Belt Worn When Working From An Aerial Lift
8	55	1926.300(b)(2)	Unguarded Reciprocating, Rotating Or Moving Parts Of Equipment
9	46	1926.602(a)(9)(i)	No Audible Alarms For Material Handling Equipment
10	38	1926.405(b)(2)	No Covers Provided for Pull Boxes, Junction Boxes, and Fittings No Fall Protection For Employees Working Above 6 Feet In Residential Construction
11	38	1926.501(b)(10)	
12	36	1926.602(a)(9)(ii)	Earthmoving Equipment Used When The Rear View Is Obstructed
13	36	1926.1053 (b)(1)	Ladder Side Rails Do Not Extend Three Feet Above Upper Surface
14	35	1926.95(a)	No Personal Protective Equipment
15	30	1926.100(a)	No Hard Hats Required
16	28	1926.405(b)(1)	Unused Openings in Cabinets, Boxes, and Fittings Not Effectively Closed
17	28	1926.701(b)	No Guard Provided For Rebar
18	27	1926.652(a)(1)	Inadequate Cave-In Protection On Excavation Site
19	25	1926.451 (e)(1)	Ladder Not Provided To Access Scaffold
20	24	1910.1200(f)(5)	No Label on Hazardous Chemical Containers
21	24	1926.602(c)(1)(vi)	Designs Of Industrial Trucks Required To Meet The American National Standards Institute (ANSI) B56.1-1969
22	23	1926.501(b)(11)	No Fall Protection For Employees Working On Steep Roofs No Evaluation of Forklift Operator's Performance Conducted at Least Every 3 Years
23	21	1910.178(I)(4)(iii)	
24	19	1926.152(g)(9)	No Signs Posted to Prohibit Smoking Near Flammable and Combustible Liquids No Personal Fall Arrest or Guardrail System for Employees Working on Scaffold 10 Feet Above Lower Level
25	19	1926.451(g)(1)(vii)	